

**REHABILITATION OF LAGOS-OTTA-ABEOKUTA ROAD IN LAGOS/OGUN STATES
SECTION II: OTTA-ABEOKUTA CONTRACT NO. 3278A (ADDENDUM NO. 4)
WEEKLY PROGRESS PHOTOGRAPHS FOR THE WEEK ENDING 2ND OCTOBER, 2021.**



**EXCAVATION OF EXISTING FAILED SHOULDER BETWEEN CH 26+000 AND CH 26+210
(LAGOS BOUND)**

**REHABILITATION OF LAGOS-OTTA-ABEOKUTA ROAD IN LAGOS/OGUN STATES
SECTION II: OTTA-ABEOKUTA CONTRACT NO. 3278A (ADDENDUM NO. 4)
WEEKLY PROGRESS PHOTOGRAPHS FOR THE WEEK ENDING 2ND OCTOBER, 2021.**



**SPREADING AND COMPACTION OF STONE BASE IN PROGRESS BETWEEN
CH 26+000 AND CH 26+070 (LAGOS BOUND)**

**REHABILITATION OF LAGOS-OTTA-ABEOKUTA ROAD IN LAGOS/OGUN STATES
SECTION II: OTTA-ABEOKUTA CONTRACT NO. 3278A (ADDENDUM NO. 4)
WEEKLY PROGRESS PHOTOGRAPHS FOR THE WEEK ENDING 2ND OCTOBER, 2021.**



**SPRAYING OF MC1 AS PRIME COAT ON CARRIAGE-WAY BETWEEN CH 21+924 – CH 21+940
AND CH 21+270 – CH 21+965 (LAGOS BOUND)**